



NOTES:

1. See Section 6 – Engineering in the LOGIX Product Manual for reinforcement details.
2. Treating the soil ahead of time is another method of avoiding termite related problems.
3. The use of 4" Height Adjusters will ensure there is an 8" gap exposing any termite presence in the wall.
4. Please refer to local building codes for more information on termite control.